



12

Fig. 1



22

Fig. 2






Fig. 3

005220-2525T560

N4699
Sheet 4 of 13




Fig. 4

000000-25291 REFERENCE SURFACE

REFERENCE WEAR COVER

PULSABLE, DIFFUSED, LIGHT TRANSMITTER ARRAY #2

PULSABLE LIGHT TRANSMITTER ARRAY #1

RECEIVER ARRAY

MOVABLE MIRROR

WEAR COVER

MOVING BELT WITH MATERIAL

SURFACE GLOSS DETECTION METHOD

FIG. 5

N4699
Sheet 6 of 13

0051657-02200





Fig. 6



000000-259550

ORIENTATION




Fig. 8




FIG. 9




FIG. 10

00515257-022900

TEST MODE



Status: Stopped

No sections are in service

START →

STOP →

BYPASS →

RUN ←

FEED ←

FAULT ←

Mirror
Position:

- Reference
- Belt

Main Power

Air Pressure

Valve Voltage

Air Conditioner

Information:

Channels: ? of 64

Air Valves: 0 of 32

Run Time: 0:00:00

< Sort 1 >

Eject all colors

START

Local

Remote

Sort Select
Screen

Service
Screen

006220-2291560

324, 326

FIG. 11

328

Sort Select

MSS, Inc.



| | |
|--|------|
| 1 C PASS WHITE PAPER; EJECT ALL COLORED PAPER | 9 C |
| 2 C EJECT ALL WHITE PAPER; PASS ALL COLORED PAPER | 10 C |
| 3 C EJECT BROWN CARDBOARD | 11 C |
| 4 C EJECT ANY GLOSSY MATERIAL | 12 C |
| 5 C EJECT NEWSPRINT | 13 C |
| 6 C | 14 C |
| 7 C | 15 C |
| 8 C | 16 C |

Edit Parameters

[Back to Main](#)

324, 330

FIG. 12






FIG. 15